



Panther Pro

Groupe **Vsf**

PRODUCT DATA SHEET / 5555-100

SURFACE PREPARATION PASTE



EXCLUSIVE

Panther Pro

The paste allows you to prepare your bonding surface in 4 easy steps

1. Check for surface contamination by spraying glass cleaner along the fret line
2. Apply a small amount of product.
3. Using a paper towel spread the paste over all the contaminated areas.
4. Clean the fret with glass cleaner until all the paste has been removed. Repeat step 1 to ensure all contamination has been removed.



Tel: +44 (0)1246 559337 - sales@panther-pro.co.uk

panther-pro.co.uk

Groupe **Vsf**

VSF Panther Pro Glass&Boost